



Public Notice

Release Date: July 5, 2007

Dorel Distribution Canada and Transport Canada wish to advise the public of a potential installation problem involving the Designer 22 infant restraint system models listed below produced between May 12, 2005 (2005 05 12) and September 12, 2006, (2006 09 12) inclusive. This is not a safety related issue.

The model name and model Numbers of Travel systems sold with Designer 22 Infant car seats are (Travel System Model # - Infant Car seat Model #);

Cosco Agility Travel System, 01708CRBL - 22320CRBL;

Cosco Spirit Travel System 01953CAMB - 22H31AMB;

Eddie Bauer Lightweight Travel System -01720CLNG - 22625CLNG; -01720CLRS - 22625CLRS; 01720CBLD -22H65BLD; 01720CHPN -22H65HPN; 01720CBGL - 22H65BGL; -01720CMAC -22H65MAC

Safety 1st Acella LX Travel System 01915CVIN -22H32VIN; 01915CJAC - 22H32JAC;

Safety 1st Eurostar Plus Travel System 01916CCRM -22H32CRM;

Safety 1st Eurostar Travel System 01911CBKP - 22H32BKP; 01911CCMB – 22H32CMB; 01911CKIN -22H32KIN;

Safety 1st Eurostar with Reversible Handle 01700CVER -22H32VER;

Quinny Freestyle 4XL Travel System 01936CPDK -22H56PDK;

Model names and Model numbers of Designer 22 Infant car seats sold without a travel system are:

Cosco Designer 22-22030CMFC;

Safety 1st Designer 22-22325CTRE; 22H32TIM; 22H55SLP;

The model number and date of manufacture can be found on a label affixed to the back of the infant carrier. On May 12, 2005, the length of the retaining strap (also referred to as the "pigtail" strap) that attaches the UAS belt to the detachable base was shortened to 23 cm (9 in.) from 38 cm (15 in.) in length. The change to a shorter "pigtail" strap may result in some difficulty when installing the infant car seat using the base with the UAS belt in certain vehicles. Specifically, the shorter "pigtail" strap may prevent the UAS hook from reaching the vehicle anchorage.

Dorel Distribution Canada is asking anyone who may experience difficulty installing the infant car seat using the UAS belt to please contact Dorel Juvenile Group Consumer Relations Center by phone at 1-800-544-1108 or by fax at 1-800-207-8182. A replacement UAS belt with a longer "pigtail" strap will be sent free of charge. While waiting for the replacement UAS belt, the infant car seat may be installed in the vehicle using the seat belt instead of the UAS belt. This is not a safety related issue.